# **Accessibility Survey**

# Americans with Disabilities Act And Title 24 of the California Building Code



Prepared By

Disability Access Consultants, Inc. (800) 743-7067



# **City of Glendale**

**Downtown Parking Lot #1** 

200 N Central Avenue

**Inspected January 2008** 

## Programs, Services, and Activities

**Finding:** Parking Lot #1 is located at 200 North Central Avenue in

Glendale, California. The parking lot was inspected by Disability Access Consultants, Inc., on January 15, 2008.

Alternative \* Rec: (Where Available)

Full Rec: Any renovation or new construction that occurred after January 26, 1992, is subject to meet full code specifications for the California Building Code and ADAAG requirements. All recommendations in this report are based on ADAAG and CBC Title 24 requirements. Consult with your design professional to determine which elements are affected by these

requirements. It is recommended that Disability Access Consultants, Inc. is consulted for inspection of any new

construction or renovation at the facility.



Parking Lot # 1

Citations: ADAAG 4.1.2; ADAAG 4.1.3; ADAAG 4.1.5; ADAAG 4.1.6

Minimum Quantity: Maximum Quantity **Minimum Estimated Cost:** \$0.00 **Maximum Estimated Cost:** \$0.00 Record Number:: 55

Priority:

# **Parking**

**Finding:** There is one accessible parking space out of 59 parking spaces which does not meet the minimum number for compliance. The accessible parking space measures only 100 inches wide and 182 inches long with a 53 inch wide access aisle. There is no designated "vanaccessible" parking space and the access aisle does not contain "NO PARKING" in 12" high white letters.

Alternative \* Rec: (Where Available)

**Full Rec:** Three out of 59 total parking spaces are required to be designated exclusively for accessible parking. Restripe the existing accessible space and create two additional accessible spaces, each measuring at least 108 inches wide and 216 inches long. Designate one parking space as "van-accessible". The van-accessible space shall provide an access aisle measuring at least 96 inches wide on the passenger side of the space. The two additional parking spaces shall each provide an access aisle measuring at least 60 inches wide, that may be shared. Add the words NO PARKING in 12 inch high white letters at the entrance to each accessible parking access aisle.



Accessible Parking

Citations: CBC 1129B; ADAAG 4.6; ADAAG A4.6

Minimum Quantity: 1 Maximum Quantity 3 **Minimum Estimated Cost:** \$270.00 **Maximum Estimated Cost:** \$810.00 49

Record Number::

# Facility Name: Downtown Parking Lot #1

# **Parking**

Finding: There is no accessible route between the accessible

parking space and the public right of way. The path of

travel crosses a curb.

Alternative \*
Rec:
(Where
Available)

Full Rec: Install a compliant path of travel from the sidewalk

(public right of way) to the accessible parking space.



Accessible Parking

Citations: CBC 1129B.4.3; ADAAG 4.7.1

Minimum Quantity:

Maximum Quantity

Minimum Estimated Cost: \$1,033.00

Maximum Estimated Cost: \$1,033.00

Record Number:: 50

Priority:

# **Parking**

Finding: The surface of the accessible parking space has a slope

of 2.9%.

Alternative \*
Rec:
(Where
Available)

Full Rec: Pave the parking lot at the accessible spaces to provide

a level surface. Parking surfaces and access aisles shall be located in areas not exceeding 2% slope in all directions (see CBC 1129B and ADAAG 4.6.3).



Accessible Parking

Citations: CBC 1129B; ADAAG 4.6.3

Minimum Quantity: 1
Maximum Quantity 1
Minimum Estimated Cost: \$900.00
Maximum Estimated Cost: \$900.00

Record Number:: 5

### Facility Name: Downtown Parking Lot #1

### **Parking**

Finding: The vertical clearance at the accessible parking space

is only 79 inches due to tree branches.

Alternative \*
Rec:
(Where
Available)

Full Rec: Maintain the tree branches to provide at least 98 inches

of vertical clearance at the accessible parking space.



Accessible Parking

Citations: ADAAG 4.6.5

Minimum Quantity:

Maximum Quantity

Minimum Estimated Cost: \$0.00

Maximum Estimated Cost: \$0.00

Record Number::

52

Priority:

# **Parking**

**Finding:** There is no warning signage posted at the entrance

from Central Avenue regarding unauthorized use of accessible parking spaces in the parking lot.

Alternative \*
Rec:
(Where
Available)

**Full Rec:** Post a sign in a conspicuous place at the entrance of the parking lot, or immediately adjacent to and visible

from each accessible space. The warning sign shall measure at least 17 inches by 22 inches in size and consist of lettering at least 1 inch in height that states the following; "Unauthorized vehicles parked in designated accessible spaces not displaying distinguishing placards or license plates issued for persons with disabilities may be towed away at owner's expense. Towed vehicles may be reclaimed at or by telephoning \_\_\_\_\_ ." Fill in the blank spaces with appropriate information as a permanent part of the sign

and be sure to add the CVC 22511.8(a)(d) to the sign.



Accessible Parking

Citations: CBC 1129B.5; ADAAG 4.6.4 CVC 22511.8(a)(d)

Minimum Quantity:1Maximum Quantity2Minimum Estimated Cost:\$150.00Maximum Estimated Cost:\$300.00

Record Number::

# Facility Name: Downtown Parking Lot #1

#### Path of Travel

Finding: There is no accessible route from the public right of way

to the parking lot or to the accessible parking space.

Alternative Post directional signage.

Rec: (Where Available)

Full Rec: Provide at least one accessible route from the public

right of way to the parking lot and to the accessible parking spaces. Make certain to post signage indicating the direction of the accessible route to the public right of way. Signs shall include the International

Symbol of Accessibility.



Accessible Route from the Public Right of Way

Citations: CBC 1114B.1.2; CBC 1117B.5.7; CBC 1127B.3; ADAAG 4.1.2(7); ADAAG 4.3.2; ADAAG 4.14.1

Minimum Quantity:

Maximum Quantity

Minimum Estimated Cost: \$107.00

Maximum Estimated Cost: \$0.00

Record Number:: 54