

APPENDIX H

Sewer Trouble Spot Work List

City of Glendale

APPENDIX H - Sewer Trouble Spot Work List

The following working and historical documents constitute the contents of this appendix but are Located or stored as follows:

1. Electronic copy of the master set of monthly trouble spot work lists can be found at:

G:\1-WASTEWATER\YYYY\Crew Supervisor & WW Supt. Shared

2. The set of the 12 most recent work lists is kept in a three-ring binder in a wall file holder on the door to the Crew Supervisor's Office in the Wastewater Shop Office.
3. Three (3) years of program records are maintained in a labeled file drawer in the Wastewater Shop Office.

Wastewater Maintenance Group

Month: February 2014
(Year)



Hydrojetting

Item No.	Street No.	Street Name	LINE LOCATION	Freq.	LF	On List (MMYY)	Compl't'd By (initials)	Date Compl't'd	Comments/Follow-up
RT 1	400	E. CYPRESS	ST	11	581		TNT	2-24-14	
RT 2	1100	N. HOWARD	ST	1	832	R8/12	TNT	2-24-14	
RT 3	800	BURCHETT	ST	2	743	R07/13	TNT	2-19-14	Feb & July 090762-090761
RT 4	1100	S. CENTRAL AVE	ST	2	453		TNT	2-24-14	
MU 5	700-800	E. CHESTNUT	ST	2	658	R8/12	MU-BH	2-18-14	M.H.#s 030423-030420
MU 6	400-1000	RALEIGH ST	ST	2	2728		JG-BH	2-14-14	
AH 7	100-500	N. JACKSON	ST	2	3066		AH-JG	2-18-14	
AH 8	100-600	N. KENWOOD	ST	2	3427		AH-JG	2-14-14	
MU 9	1100-1200	E. CALIFORNIA AVE	ST	2	798		MU-BH	2-19-14	
MU 10	1100-1200	E. LEXINGTON AVE	ST	2	1457		MU-BH	2-19-14	
AH 11	3500	EL LADO DR	ST	1	1284		AH-JG	2-14-14	
RT 12	1400	TORRES DR	ST	2	746		TNT	2-26-14	
AH 13	100-200	S. GLENDALE	AVE	5	760		AH-JG	2-18-14	W.SIDE ALLEY BEHIND POLLO LOCO
MU 14	1700	SANTA PAULA #2218	PL	2	230		MU-JG	3-4-14	RUN FROM PARK
RT 15	4200	Lauderdale	Ave	2	463		MU-AH	2-27-14	Encinal & Lauderdale 1st reach.
RT 16	3541	Emerald Isle	R/W	1	407		TNT	2-24-14	Clean whole easement
MU 17	600	W. KENNETH RD	RD	2	332	Mar-11	MU-BH	2-19-14	M.H.#s 090333 to 090339
MU 18	1000	Linden		11	630		MU-BH	2-18-14	
MU 19	1800	Gardenal		2	595	R02/13	MU-BH	2-18-14	MH#s 010377-010387
MU 20	1655	Las Flores	R/W	2	484	R07/13	MU-BH	2-20-14	Feb/July
Total					20554				

Rodder

Item No.	Street No.	Street Name	LINE LOCATION	Freq.	LF	On List (MMYY)	Compl't'd By (initials)	Date Compl't'd	Comments/Follow-up
1	1315	E. ACACIA END OF DAY	R/W	1	752		MU-JG	3-4-14	CRC, do visual
2	1500	N. MARYLAND #1915	R/W	1	128		MU-JG	3-4-14	
3	5-600	LUTON		4	1105		MU-JG	3-4-14	Freq. (4) May, Aug, Nov (CRC 8-1-13)
4	1100	ESMERALDA #2017	DR	3	535		MU-JG	3-4-14	Freq. (3) May, Aug
5		OFF ARBOLES							
					2520				

Inactive Items

Reviews:
WW Crew Super. 
WW Maint. Supl. 

Wastewater Maintenance Group

Month: February _____

Item No.	Street No.	Street Name	LINE LOCATIO N	Freq.	(Year) On List (MMYY)	List From	Date Removed	Comments/Follow-up
1								
2								
3								
4								

Reviews:
WW Crew Super. _____
WW Maint. Supt. _____

Wastewater Maintenance Group

Month: February

(Year)

5									
---	--	--	--	--	--	--	--	--	--

Hand Rodding

Item No.	Street No.	Street Name	LINE LOCATIO N	Freq.		On List (MMYY)	Compl't'd By (initials)	Date Compl't'd	Comments/Follow-up
1									
2									
3									
4									
5									
6									
7									
8									
9									
10									

Visual Inspections

Item No.	Street No.	Street Name	R/W (Yes)	Freq.		On List (MMYY)	Compl't'd By (initials)	Date Compl't'd	Comments/Follow-up
1	3828	HILLWAY DR	R/W	1			N.V.	2-18-14	
2									
3									
4									
5									

Reviews:

WW Crew Super.

WW Maint. Supt.



City of Glendale

Monthly Trouble Spot Worklist

4 of 5

Wastewater Maintenance Group

Month: February _____
(Year)

Cell: J5
Comment: SMorra:

400 E. Cypress Run is 125 from drop MH under storm drain. Line is in front of convalescent home. Heavy Grease. Revised from dirty. To monthly, Feb. 04 (JNH).

Cell: J7

Comment: 600 Burchett:

Set up at Central and Burchett at the drop hole and run out 600 feet.
Heavy grease

Cell: J8

Comment: 1100 S. Central:

Set up on Central/Palmer and run 600 ft. Palmer has a heavy flow restricting flow on Central.

Cell: J10

Comment: 400-1000 E. Raleigh:
Multi-Family Dwellings

Cell: J11

Comment: 100-800 N. Jackson:
Multi-Family Dwellings

Cell: J12

Comment: 100-600 N. Kenwood:
Multi-Family Dwellings

Cell: J15

Comment: 5500 El Lado Dr:

Set up on Cloud and Sycamore. Clean 24" pipe that run under Verdugo channel. Heavy debris.

Cell: J16

Comment: 1400 Torres Dr:

Run from Flush tank to end of street, low spots and medium rocks in line.
Street is narrow.

Cell: J29

Comment: 1315 E. Acadia:

Line cleaned with rodder in bottom. Top half is cleaned with chain fall from
3-148-3-143-C-273-C-114-0

Cell: J30

Comment: 517 Cavanagh Rd:

Reviews: Set up in front of driveway and run out 180 ft.

WW Crew Super. _____

WW Maint. Supt. _____

2/13/2014 5:26 AM FEB